(Wragley Way)

11.4.6 The Council's Consultant Landscape Architect has inspected the site and concludes that this site would have marginal impact on the landscape and could easily be further screened from any visual impact.

(Boulton Moor)

11.5.6 The Council's Consultant Landscape Architect has inspected the site and concludes that it is a generally flat, comparatively featureless site. Although there are strong views into the site from the road these could easily be removed through appropriate roadside landscaping.

(Stenson Fields)

11.6.5 The Council's Consultant Landscape Architect has inspected the site and concludes that this site would not form an intrusive new feature on the landscape. The landscape is not visually of any great interest. Additionally, screening could be integrated into any proposals.